


R-M Color Adjustment Chart – UNO HD


Solid Colors

	Mixes			Mixes			Mixes			Mixes	
	T. Base / SC 90 80 / 20	T. Base / SC 90 20 / 80		T. Base / SC 90 80 / 20	T. Base / SC 90 20 / 80		T. Base / SC 90 80 / 20	T. Base / SC 90 20 / 80		T. Base / SC 20 80 / 20	T. Base / SC 20 20 / 80
SC 20			SC 54			SC 74			SC 90		
SC 25			SC 57			SC 77			SC 99		
SC 29			SC 59			SC 79			Mixes T. Base 100 SC 203 SC 403		
SC 31			SC 61			SC 82					
SC 41			SC 62			SC 85					
SC 44			SC 66			SC 86					
SC 46			SC 67			SC 87					
SC 49			SC 69			SC 88					

Pictogram




The color wheel of tinting bases




Color characteristics



Subtractive color mixing



Complementary colors



Perfection
made simple

